


INTERIM FLY QUIET SUMMARY

WEEK OF DECEMBER 1, 2019 (Week 5)




Note: Values above represent the average for time period.

**INTERIM FLY QUIET RUNWAY ROTATION
NOVEMBER 3, 2019 TO JANUARY 31, 2021¹
WEEK OF DECEMBER 1ST (WEEK 5)**




Fly Quiet Mode ²						
Time				Runway Rotation Adherence		
Start	Stop	Duration (hrs: mins)	Percentage of Nighttime ³	Primary Configuration ⁴	Secondary Configuration ⁴	Operations
12/2/19 - 01:41 AM	12/2/19 - 05:41 AM	4:00	45%	22%	0%	67
12/2/19 - 11:20 PM	12/3/19 - 05:46 AM	6:26	71%	3%	0%	101
12/3/19 - 10:03 PM	12/4/19 - 05:44 AM	7:41	85%	4%	0%	151
12/4/19 - 10:00 PM	12/5/19 - 05:42 AM	7:42	86%	84%	0%	140
12/5/19 - 10:00 PM	12/6/19 - 05:45 AM	7:45	86%	82%	0%	140
12/6/19 - 10:34 PM	12/7/19 - 05:41 AM	7:07	79%	23%	47%	86
12/7/19 - 10:08 PM	12/8/19 - 05:27 AM	7:19	81%	53%	0%	80
Average (Week of December 1st)						
10:49 PM	5:40 AM	6:51	76%	42%	5%	109



Notes:

- Interim Fly Quiet is a temporary program beginning November 3, 2019 through early 2021, when Runway 9R/27L is closed for extension construction. It is expected that significant runway construction, maintenance, and/or pavement rehabilitation on Runways 4L/22R and 4R/22L would impact the Interim Fly Quiet during the 2019 and 2020 construction seasons, respectively. It is not anticipated that the Interim Fly Quiet would occur during these construction periods.
- Fly Quiet Mode is the period of time in which the nighttime operations are operating in accordance with the CDA's Fly Quiet Program.
- FAR Part 150 considers nighttime hours 10:00 PM - 07:00 AM.
- Percentage of operations on designated runways within Fly Quiet Mode.
- Runway 10L/28R is available for flights that require additional runway length and have contacted CDA Operations at a minimum of 2 hours prior to arrival or departure.



Comments:

- There were 4 requests granted for alternative runways during Fly Quiet Mode.
- On the night of 12/1, the Rotation was restricted due to inclement weather.
- On the nights of 12/2 and 12/3, the Rotation was restricted due to rubber removal on Runway 9R/27L.