


# INTERIM FLY QUIET SUMMARY

WEEK OF FEBRUARY 9, 2020 (Week 15)




Note: Values above represent the average for time period.

**INTERIM FLY QUIET RUNWAY ROTATION  
NOVEMBER 3, 2019 TO JANUARY 31, 2021<sup>1</sup>  
WEEK OF FEBRUARY 9TH (WEEK 15)**




Fly Quiet Mode <sup>2</sup>						
Time				Runway Rotation Adherence		
Start	Stop	Duration (hrs: mins)	Percentage of Nighttime <sup>3</sup>	Primary Configuration <sup>4</sup>	Secondary Configuration <sup>4</sup>	Operations
2/9/20 - 10:51 PM	2/10/20 - 05:59 AM	7:08	79%	95%	0%	93
2/10/20 - 10:33 PM	2/11/20 - 05:51 AM	7:18	81%	57%	0%	88
2/11/20 - 10:29 PM	2/12/20 - 06:04 AM	7:35	84%	92%	0%	108
2/13/20 - 12:56 AM	2/13/20 - 06:19 AM	5:23	60%	13%	33%	63
2/13/20 - 11:59 PM	2/14/20 - 06:00 AM	6:01	67%	51%	0%	87
2/14/20 - 10:02 PM	2/15/20 - 05:51 AM	7:49	87%	77%	1%	137
2/15/20 - 10:23 PM	2/16/20 - 06:01 AM	7:38	85%	26%	0%	81
<b>Average (Week of February 9th)</b>						
11:01 PM	6:00 AM	6:59	78%	63%	3%	94



**Notes:**

- Interim Fly Quiet is a temporary program beginning November 3, 2019 through early 2021, when Runway 9R/27L is closed for extension construction. It is expected that significant runway construction, maintenance, and/or pavement rehabilitation on Runways 4L/22R and 4R/22L would impact the Interim Fly Quiet during the 2019 and 2020 construction seasons, respectively. It is not anticipated that the Interim Fly Quiet would occur during these construction periods.
- Fly Quiet Mode is the period of time in which the nighttime operations are operating in accordance with the CDA's Fly Quiet Program.
- FAR Part 150 considers nighttime hours 10:00 PM - 07:00 AM.
- Percentage of operations on designated runways within Fly Quiet Mode.
- Runway 10L/28R is available for flights that require additional runway length and have contacted CDA Operations at a minimum of 2 hours prior to arrival or departure.



**Comments:**

- There were 0 requests granted for alternative runways during Fly Quiet Mode.
- On the nights of 2/12 and 2/13, the Rotation was restricted due to inclement weather.
- On the night of 2/15, the Rotation was restricted due to construction on Runway 10L/28R.