


# INTERIM FLY QUIET SUMMARY

WEEK OF MARCH 8, 2020 (Week 19)




Note: Values above represent the average for time period.

**INTERIM FLY QUIET RUNWAY ROTATION  
NOVEMBER 3, 2019 TO JANUARY 31, 2021<sup>1</sup>  
WEEK OF MARCH 8TH (WEEK 19)**



Fly Quiet Mode <sup>2</sup>						
Time				Runway Rotation Adherence		
Start	Stop	Duration (hrs: mins)	Percentage of Nighttime <sup>3</sup>	Primary Configuration <sup>4</sup>	Secondary Configuration <sup>4</sup>	Operations
3/8/20 - 10:22 PM	3/9/20 - 05:34 AM	7:12	80%	0%	95%	110
3/9/20 - 11:12 PM	3/10/20 - 05:42 AM	6:30	72%	0%	96%	82
3/10/20 - 10:37 PM	3/11/20 - 05:37 AM	7:00	78%	15%	16%	67
3/11/20 - 10:36 PM	3/12/20 - 05:37 AM	7:01	78%	0%	65%	113
3/12/20 - 10:47 PM	3/13/20 - 05:41 AM	6:54	77%	0%	28%	96
3/13/20 - 10:42 PM	3/14/20 - 05:31 AM	6:49	76%	5%	25%	92
3/14/20 - 10:59 PM	3/15/20 - 05:36 AM	6:37	74%	90%	0%	71
Average (Week of March 8th)						
10:45 PM	5:36 AM	6:51	76%	13%	50%	90



**Notes:**

- Interim Fly Quiet is a temporary program beginning November 3, 2019 through early 2021, when Runway 9R/27L is closed for extension construction. It is expected that significant runway construction, maintenance, and/or pavement rehabilitation on Runways 4L/22R and 4R/22L would impact the Interim Fly Quiet during the 2019 and 2020 construction seasons, respectively. It is not anticipated that the Interim Fly Quiet would occur during these construction periods.
- Fly Quiet Mode is the period of time in which the nighttime operations are operating in accordance with the CDA's Fly Quiet Program.
- FAR Part 150 considers nighttime hours 10:00 PM - 07:00 AM.
- Percentage of operations on designated runways within Fly Quiet Mode.
- Runway 10L/28R is available for flights that require additional runway length and have contacted CDA Operations at a minimum of 2 hours prior to arrival or departure.

**Comments:**

- There were 0 requests granted for alternative runways during Fly Quiet Mode.
- On the nights of 3/10, 3/12, and 3/13, the Rotation was restricted due to construction on Runway 10C/28C.