


INTERIM FLY QUIET SUMMARY

WEEK OF MARCH 22, 2020 (Week 21)



Note: Values above represent the average for time period.

www.flychicago.com/oharenoise


**INTERIM FLY QUIET RUNWAY ROTATION
NOVEMBER 3, 2019 TO JANUARY 31, 2021¹
WEEK OF MARCH 22ND (WEEK 21)**




Fly Quiet Mode²

Time				Runway Rotation Adherence		
Start	Stop	Duration (hrs: mins)	Percentage of Nighttime ³	Primary Configuration ⁴	Secondary Configuration ⁴	Operations
3/22/20 - 11:07 PM	3/23/20 - 06:11 AM	7:04	79%	0%	22%	87
3/23/20 - 10:10 PM	3/24/20 - 06:06 AM	7:56	88%	32%	36%	115
3/24/20 - 10:09 PM	3/25/20 - 06:01 AM	7:52	87%	26%	35%	113
3/25/20 - 10:00 PM	3/26/20 - 05:22 AM	7:22	82%	37%	0%	92
3/26/20 - 10:27 PM	3/27/20 - 06:03 AM	7:36	84%	0%	70%	82
3/27/20 - 10:18 PM	3/28/20 - 06:01 AM	7:43	86%	0%	65%	65
3/28/20 - 10:00 PM	3/29/20 - 06:26 AM	8:26	94%	48%	1%	92
Average (Week of March 22nd)						
10:18 PM	6:01 AM	7:43	86%	22%	31%	92

Primary⁵




Secondary⁵



Notes:

- Interim Fly Quiet is a temporary program beginning November 3, 2019 through early 2021, when Runway 9R/27L is closed for extension construction. It is expected that significant runway construction, maintenance, and/or pavement rehabilitation on Runways 4L/22R and 4R/22L would impact the Interim Fly Quiet during the 2019 and 2020 construction seasons, respectively. It is not anticipated that the Interim Fly Quiet would occur during these construction periods.
- Fly Quiet Mode is the period of time in which the nighttime operations are operating in accordance with the CDA's Fly Quiet Program.
- FAR Part 150 considers nighttime hours 10:00 PM - 07:00 AM.
- Percentage of operations on designated runways within Fly Quiet Mode.
- Runway 10L/28R is available for flights that require additional runway length and have contacted CDA Operations at a minimum of 2 hours prior to arrival or departure.



Comments:

- There were 5 requests granted for alternative runways during Fly Quiet Mode.
- On the night of 3/22, the Rotation was restricted due to inclement weather.
- On the nights of 3/25 and 3/28, the Rotation was restricted due to rubber removal on Runway 10C/28C.